



HYTORC MXTP-1

PRESSURE IN PSI	PRESSURE/TORQUE CONVERSION CHART			PRESSURE IN BAR
	FT. LBS.	KGM	NM	
1500	205	28	278	104
1600	219	30	297	110
1800	247	34	335	124
2000	275	38	373	138
2200	303	42	411	152
2400	331	46	449	166
2600	359	50	487	179
2800	388	54	526	193
3000	416	58	564	207
3200	444	61	602	221
3400	472	65	640	235
3600	500	69	678	248
3800	528	73	716	262
4000	556	77	754	276
4200	584	81	792	290
4400	612	85	830	304
4600	640	89	868	317
4800	668	92	906	331
5000	696	96	943	345
5200	724	100	981	359
5400	751	104	1018	373
5600	778	108	1055	386
5800	806	111	1093	400
6000	833	115	1129	414
6200	860	119	1166	428
6400	887	123	1202	442
6600	914	126	1239	455
6800	941	130	1276	469
7000	968	134	1312	483
7200	994	137	1347	497
7400	1021	141	1384	511
7600	1047	145	1419	524
7800	1074	149	1456	538
8000	1100	152	1491	552
8200	1126	156	1526	566
8400	1152	159	1562	580
8600	1179	163	1598	593
8800	1205	167	1633	607
9000	1231	170	1669	621
9200	1257	174	1704	635
9400	1282	177	1738	649
9600	1308	181	1773	662
9800	1334	184	1808	676
10000	1359	188	1842	690

This chart supercedes all prior version regarding this tool 03/31/2008

Southwest Texas	West Texas	Main Office	Southeast Texas	Central & East Texas
4802 Baldwin Blvd. Corpus Christi 78408 361-888-5080	3508 S County Rd 1290 Odessa, TX 78765 432-561-8481	12420 Texaco Rd Houston, TX 77013 713-453-6677	2484 W Cardinal #4 Beaumont, TX 77705 409-840-9699	7900 Rodeo Trl. #500 Mansfield, TX 76063 682-334-2679